

Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



WORK ORDER INFORMATION

Work Order Name: WO/80008KN0796/1

Work Order Type: Weatherization

Audit Name: 80008KN0796-Audit

CLIENT INFORMATION

Client Name:

Address:

Client ID: 80008KN0796

Alt. Client ID: KNOX

AGENCY INFORMATION

Agency: Knoxviile/Knox County CAC

Address: P.O.Box 51650

Knoxville, TN 37950-1650

Agency Phone: (865) 244-3080

Fax: (865) 544-1647

Email Address: jason.estes@cachousing.org

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Single Family Dwelling

Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.

City

Mobile Home built in 1968

An EPA Certified Firm/Renovator is required.

Measures

,	Measure 1 Mob	ile Home Belly Repair(C	TY 576S	F)	Componen	ts			Inspected
C	comment Repair b fastners	elly with a durable product. Tape not allowed as a fa	et such as astner.	s Tyve	k. Secure wi	th mecha	anical		
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Mobile Home Belly Repair	SqFt	576					
		Repair belly with a durable product such as Tyvek. Secure with mechanical fastners. Tape not allowed as a fastner.							
2	Labor	Labor	SqFt	576					
0	ther Detail								
			ı	Measur	e Sub Total:	- Caro		Sub Total: [
	Field Notes:								

Measure 2 DW	/H Pipe Insulation		Components					Inspected	
Comment				-					
				Estimated	•		Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	DWH Pipe Insulation	Each	1						
	Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.				•	·	· · · · · · · · · · · · · · · · · · ·		
2 Labor	DWH Pipe Insulation	Each	1						
Other Detail									
			Measur	e Sub Total:			Sub Total:		
Field Notes:			***				****		

Report Run On: 5/8/2010

A	<i>l</i> leasure	3 Bel	ly Fiberglass R-19 Batt			Componen	ts	_		Inspected
Co		seal pe Resnet contact necess voids, c	es labor cost. Contractor's netration in floor before in Grade 1 Standards. Inst with the subfloor above (ary supports (e.g. staves or compressions. Refer to Is and Southeast Field G	nstalling in ulation is ir paper side for blanke Appendix	sulationstalle e agair ts). In	n. Contracto d to maintair est subfloor) sulation to h	or to instanted permanding including ave NO g	II using ent gaps,		
						Estimated	<u> </u>		Actual	
#	Material / I	Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation		Floor Insulation - Fbergls,R-19 Batt	SqFt	576	Type (Adapta				
2	Labor		Floor Insulation - Fbergls,R-19 Batt	SqFt	576					
O	her Detail									
	****	***	1700							
		70.4					**			
					Measur	e Sub Total:			Sub Total:	
1	Fleld Notes	s:		1194						111111111111111111111111111111111111111

	Measure 4 D	WH Tank Insulation			Componen	ts		1	Inspected
C	comment exten	nd pressure relief pipe as nee	eded						
					Estimated	•		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DWH Tank Insulation	Each	1					
		Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.			[
2	Labor	DWH Tank Insulation	Each	1					
_	Other Detail								
				Measui	e Sub Total:			Sub Total:	
	Fleld Notes:	PA	**//-	.,	· · · · · · · · · · · · · · · · · · ·	With			

	Measure	5 Re	frigerator Replacement			Componer	its			Inspected
Comment •Kenmore or equivalent (must submit equivalent to Housing Director for approval). Deliver and install new refrigerator and ensure handles are on the appropriate side. Provide client education on the settings of the refrigerator and set the temperature controls appropriately. Contractor to remove all packaging materials and old refrigerator from premises. Refrigerant charge must be removed and reclaimed by a certified technician before refrigerator goes to dump. Must provide written documentation from the certified technician with technician certification license number and landfill disposal certification. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide. Refer to the Clean Air Act USC Title 42, Section 7671g. Must be Energy Star.										
			0,			EstImated	1		Actual	
#	Material /	Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Refrigera	itors	Kenmore - 68172	Each	1					
2	Labor		labor	Each	1				70.11	
2	ther Detail	!								
L	****									****
					Measur	e Sub Total:		3	Sub Total:	
	Field Note	s:								

Measure	6 Fix Any Other Heating System Problem Components	Inspecte
	•Includes labor cost. Must be installed by a licensed mechanical contractor. Must perform an ACCA Manual J and submit with invoice. Must be equal to Amana or Goodman 13 Seer Split Heat Pump (must submit equivalent to Housing Director for approval), 10 KW emergency heat. Size is approximately 2.0 ton. Final size will be determined by the ACCA Manual J. Includes complete duct system. Must perform an ACCA Manual D and submit with invoice. Must meet local codes. Liquid white Mastic to be applied to entire inside of boot to seal all seams. Top of boot where it meets subfloor to be caulked with appropriate caulk. Boots to be insulated on outside of boot to R-6. This is best performed with 2-part close cell foam. No changes allowed. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.Install thermostat. Must be equal to Honeywell's PRO 4000 Programmable Thermostat (must submit equivalent to Housing Director for approval). Must educate client on operation of thermostat.	

				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Unspecified	Replacement of Heating System (+)	Each	1					
2	Labor	labor	Each	1					
0	ther Detail								
			ı	Measur	Sub Total:		S	ub Total:	
	Fleld Notes:	**	2007 - 2	1100					

	Measure 7 Fix I	mproper Venting (Clothe	s Dryer	')	Componen	ts			Inspected
•	protrudii is 15 fee	ents installed with damper ng through pipe. Must be v et. No changes allowed. F rization Materials and Sou	ented to lefer to A	outsio Attachr	de of home. Nent A- Stand	<i>M</i> aximun	ı length	l	10001
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Dryer Vent w/ Metal Piping (upto 15' in length)	Each	1		*****			
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Labor	Each	1					
(Other Detail	_							
L									
Γ									
	***************************************			Measur	e Sub Total:			Sub Total:	
	Field Notes:				***	***			

Report Run On: 5/8/2010

· · · · · · · · · · · · · · · · · · ·	or Barrier Needed ement/Crawlspace)(Q1	ΓY 576SF)		Componen	ts	, , , , , , , , , , , , , , , , , , ,	, , , , , , , , , , , , , , , , , , , ,	Inspected
walls an earth. M	6 mil poly. Must be insta d support piers. Must be ust be secured at all sea rization Materials and So	e securely ıms. Refer	fasten to Att	ed. Must be achment A- S	cleated	down to	1	
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Basement /Crawlspace Vapor Barrier	SqFt	576					
2 Labor	Labor	SqFt	576					
Other Detail								
			Measur	e Sub Total:	****	S	Sub Total:	
Field Notes:			- 10.0	7 - 22 - 2			_	
		Work Ore	der Gra	nd Total:		Grand	l Total:	